UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 5 77 W. JACKSON BOULEVARD CHICAGO, ILLINOIS 60604

RCRA FOCUSED COMPLIANCE INSPECTION REPORT

FACILITY NAME:

MID AMERICA IBC

FACILITY U.S. EPA ID NO.:

None

FACILITY TYPE:

Non-Notifier

FACILITY ADDRESS:

2300 West Cornell Street

Milwaukee, Wisconsin 53209

U.S. EPA REPRESENTATIVE:

Walt Francis

DATE OF INSPECTION:

February 24, 2017

NAICS CODE:

332439 - Other Metal Container Manufacturing

PREPARED BY: WAKE

Walt Francis

Environmental Scientist

APPROVED BY:

Julie Morris, Chief

Compliance Section 2

RCRA Branch

Data

Purpose of Inspection

This inspection was an evaluation of Mid America IBC's compliance with hazardous waste, used oil, and universal waste regulations found in the Wisconsin Administrative Code (WAC) and the Code of Federal Regulations (CFR). The inspection team included inspectors from the Wisconsin Department of Natural Resources (WDNR), the U.S. Department of Transportation Pipeline and Hazardous Materials Safety Administration, and myself. The inspection was an EPA lead Resource Conservation and Recovery Act (RCRA) focused compliance evaluation inspection (FCI). The site never notified as a generator of hazardous waste.

Participants

United States Environmental Protection Agency (U.S. EPA) Inspectors -Walt Francis, RCRA Program James Entzminger, EPCRA Program Kathy Halbur, Superfund Emergency Response Manojkumar Patel, CAA Program

United States Department of Transportation (U.S. DOT) Inspectors – Laura Kwilinski, PHMSA Mark Razny, PHMSA

Wisconsin Department of Natural Resources (WDNR) Inspectors – Edward Lynch, Waste Program
George Volpentesta, Air Program
Bryan Hartsook, Wastewater Program
Steve Mueller, Remediation and Redevelopment Program
Benjamin Benninghoff, Stormwater Program

Representatives of Mid-America IBC – Rodney Knash, Operator Linda Benfield, Attorney Foley and Lardner, LLP Amanda Beggs, Attorney Foley and Lardner, LLP Siva Sambasivam, Greif

Site Description/Background Information

Mid-America Steel Drum Company was established in 1975. Mid-America Steel Drum has four locations in Milwaukee County (3950 S. Pennsylvania Avenue, St. Francis, 2529 E. Norwich Avenue, St. Francis, 8570 S. Chicago Road, Oak Creek, and 2300 W. Cornell St., Milwaukee, Wisconsin). The Cornell Street facility receives 250-gallon plastic and metal totes. The totes are stored prior to processing. Tote processing includes the removal of any liquid contents with a shop vacuum apparatus. The removed liquids are accumulated in 250-gallon totes and sent off-

site as a "Non-Hazardous Waste" to Badger Disposal. The next step includes an internal cleaning with soapy water and caustic. The used cleaning solution is pumped over a paper filter which removes debris. The exterior of the totes are then power washed. Based on customer specifications, either a reused plastic tote or a new plastic tote is placed in the metal tote cage and then sold to the customer. Mid-America personnel told the inspectors that if any tote arrives that contains corrosive or flammable material they are shipped to National Container, Chicago, Illinois. Mid America IBC also operates a "Cut and Scrape Operation" at the Milwaukee facility. Totes which have a residue on the bottom are placed in a saw apparatus which cuts off the bottom of the tote. Workers scrape any remaining residue into 55-gallon drums. The recovered plastic is sold to "Indy Drum". Mid-American IBC employees told the inspectors that any totes that come in as "Heavy" that do not meet the RCRA empty standards are rejected. Mid-America IBC also has a Maintenance Shop where they accumulate used fluorescent lamps. Mid-America IBS processes about 80 totes per day, operates Monday through Friday 6:00 am to 3:30 pm, has seven employees, and has been at this location for 5 years. The building occupies 30,000 square feet, and 2.66 acres. According to Mid America IBC personnel any shipping papers are stored at the Oak Creek facility.

The Milwaukee facility generates cut and scrape waste material and tote vacuuming residue, plastic and metal scrap, and used washwater. Cut and scrape residues and tote liquid residue are shipped to Badger Disposal, plastic and metal scrap are sent off-site to auto scrap yard, and the used wash water and any preflush is picked up by Advanced Waste Disposal.

Opening Conference

U.S. EPA, U.S. DOT, and WDNR representatives arrived at the Mid America IBC facility at approximately 8:55 am. The inspection group entered the facility through the truck gate and entered the facility by the loading dock. The inspectors were taken to the lunch room. The inspectors introduced themselves to Mr. Rodney Knash and Ms. Linda Benfield. A short time later, Mr. James Entzminger arrived at the facility. Inspector Francis presented his credentials to Ms. Benfield. Inspector Francis informed them of the nature, scope, and procedures of the inspection. The inspection was conducted by U.S. EPA, U.S. DOT and WDNR personnel. Mr. Knash provided the inspectors with an in depth review of the facility, and provided information on the various waste streams. Ms. Benfield told the inspectors that any photographs taken should be considered CBI. Mr. Rodney Knash allowed the inspector access to the facility to conduct the inspection.

Site Tour

The walk-through began at the Loading Dock area. Mr. Knash explained how totes arrive and are staged for storage (see photograph number 7). Mr. Knash took the inspectors to the Shop Vacuum Area. Mr. Knash explained how any liquid material is vacuumed out of the totes and placed in waste totes, see photographs number 1 and 2. The walk-through continued to the wash area. Mr. Knash showed the inspectors how the insides of the totes are washed with soap, caustic

and water. Mr. Knash then took the inspectors to the filter paper area and wash tanks, see photographs 3, 5, and 6. Inspector Francis observed four 250-gallon totes in this area waiting to be shipped to Badger Disposal, see photograph number 4. Mr. Knash told Inspector Francis that the totes contained tote vacuumed residues. The walkthrough continued to the Maintenance Shop. Inspector Francis observed a box of used compact fluorescent bulbs, see photograph number 8. The walkthrough continued to the "Drain Table". Residues from 250-gallon totes are drained into 55-gallon drums, see photographs 9 and 11. Mr. Knash showed the inspectors the tote cutting area, see photograph number 10. The walkthrough continued outside. Mr. Knash showed the inspectors totes waiting for processing, see photograph numbers 12 and 13. The walkthrough continued indoors, where Mr. Knash showed the inspectors two drum drying ovens and two 55-gallon containers, see photograph number 14. The inspection continued to an older area of the facility. Inspector Francis observed eight 55-galllon containers, see photograph number 15. The walkthrough continued back to the lunch room area. Inspector Francis observed one 250-gallon tote of "Drain Table Residue" waiting to be shipped out and the Cut and Scrape Area Drain Table, and a "Recertified 250-Gallon Tote M4712, see photograph numbers 16, 17, and 18.

The inspectors returned to the lunch room to review records.

Records Review

Mr. Knash provided Inspector Francis with a hazardous waste manifest for one tank truck load of non-hazardous waste water sent to Advanced Waste Services, Milwaukee, Wisconsin. A Non-Hazardous Waste Manifest for the shop vacuum residue sent to Badger Disposal, Milwaukee, Wisconsin, and an example incoming "Empty Totes For Recycle" Bill of Lading from Valspar Corp, Wheeling, Illinois. Inspector Francis asked Mr. Knash about waste determination records. Mr. Knash told Inspector Francis that he had the various waste streams analyzed recently, but did not have the results.

Closing Conference

The inspectors conducted a closing conference. Inspector Francis explained that he would review his notes from the inspection, and would be waiting for the waste determination records. Inspector Francis provided a U.S. EPA Small Business Resources, and a U.S. EPA Region 5 Pollution Prevention contact sheet to Mr. Knash.

Attachments

Photographs.

GENERATOR'S INITIAL COPY

Piee	Tease print or type. (Form designed for use on elite (12-pitch) typewriter.) To UNIFORM HAZARDOUS WIDDINGS 953 189 12 Page 1 of 15 Energy Place Phone									
· j		VIFORM HAZARDOUS 1. Senerator ID Number 9 5 3 1 8 9 2. Page WASTE MANIFEST 2. Page 1. 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	i of 13 Em	PBY 1-3073	Prawc	OI	253	2568	JJ	
		Generator's Manne and Mailing Address	Ganera	lor's Site Address (ii different ina	n mailing addres	B)			
	Z. N	id-Amance Steel Drum Co. 1800 W. Comeil St. Nive-Eas, Wil 53103 norators Phone: (414) 135-0381 Cheime			nogo salakan ayan kan salakan da kan salakan kan salakan salakan salakan salakan salakan salakan salakan salak	NOTION OF THE PROPERTY OF THE		alternations and an analysis of the second	n de publicandes societates museum	essentaria de la composição de la compos
	6. Æ	fransporer (Company Name 21930 cgd Waste Carriers, Inc. (AWC)				U.S. EPAID Number W 1000081530			301	-
	7.	Transporter 2 Company Marne				U.S. EPAID N	umber			
	8	Designated Facility Name and Site Address			U.S. EPA ID Number					
	3	dvarcad Wasse Service - Cherovorts 1801. Wee McKuthy Avo Eweskies, Wi 53208								nesenti princense
		cliay's Phone: 414-3-2-1852				l w	IRO	00136	572	
	9: H	B. U.S. DOT Description (including Proper Shipping Name, Hazerd Class, ID Number, and Packing Group (if any))		10. Contair No.	івла Туре	11. Yotal Quantity	12. Unli WL/Vol.			
	┢	Thor RCRA regulated, New COT hexardous Liquid material		· · · · · · · · · · · · · · · · · · ·			$\overline{}$	Aubten		
GENERATOR		Control of Control of Congression of Control of Congression Control of Contro		561	TT	2)a	ds	NONE		
皇	┝	2,	and the salar salar			***************************************	A CONTRACTOR AND ADDRESS OF THE PARTY OF THE	 		
넁		LINSTE, INTER					Distriction of the last of the	- 1		
	L	WASTE WATER 3. 03-07-14		<u> </u>			<u> </u>	<u> </u>		
		03-07-14		and the state of t						
	L		A. HOTEL AND CONTROL OF THE SECOND	ļ				į.	-	
		4.		£						
							-			4
	1	4. Special Handling Instructions and Additional Information Profile さん (A7409-O-8-1-CV)	galari jaran perupakan	Participation of the second of		Trailer?			erenzono-enco-accionom	
П							estov fla Vivel Sin	genrae Sula A	e where	spo j
		,					erskirsk Han ou	- ,	1 4 1 4	
	-	GENERATOR'S IOFFEROR'S CERTIFICATION: I hereby declare that the contents of this consign	mant neathful	ond proposish de	wate haribase	a hu the nonner el		description	iod parteau	
1		marked and labetediplacarded, and are in at respects in proper condition for transport according to Exporter, I cartify that the contents of this consignment conform to the terms of the ettached EPAA I cartify that the waste maintization statement identified in 40 CFR 262.27(a) (II i am a large quantition)	eppicable ir cknowledgmx	itemetional and nat int of Consent.	ional governo	ancisuger talner				
	l _G	enerator's/Officials Printed/Typed Name	Signature	ni (a) the am a pre-	on droterty Re	iiciawijie uso.	шинентинк-Аленка	Month	Day	Year
				المر الم		and ga		[.		te:
1 1-	: i	8. International Shipments Import to U.S. Export	from U.S.	Part of a	nirylexit			······································		
E	a description	(reasporter signature (for exporte only):		Date leav	ing U.S.:		este transportation de la company de la comp		b- (5-44-4 +45-4020000000000000000000000000000000000	:::Decapition(*except)
Į.	Ļ	7. Transporter Acknowledgment of Receipt of Materials ransporter 1 Printed Typiad Name	W		- jlanes	Handrigh and the section of the sect		TiE		<u> </u>
TRANSPORTER		inisposes (Filingui guint	Signature	1. 1.1	ŧ.			Manth	Day [-	Year
AME		ransporter 2 Printed/Typed Name	Signature					Honti	Day	Year
F	1									
1	18. Discrepancy									landromper mogra
	18a. Discrepancy Indication Space Quantity Type Residue Partial Rejection Full Rej] Full Rejec	Son
				Manifest Reference	o Number					***************************************
1	۱۱ ال	8b. Allemate Facāity (or Generator)				U.S. EPAID	Number			
CAP41 FFV	ŽĮ,	Eclity's Phone:				ŀ				
		8c. Signature of Atlemate Facility (or Generator)	Carles and Albanian				**************************************	Mon	th Day	Year
PAL	5									***
		19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)								
36	18c. Signature of Atternate Facility (or Generalor) 19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems) 1. 2. 3. 4.									
		20. Designated Facility Owner or Operator: Cartification of receipt of hazardous materials covered by the manifest except as noted in Rem 18a								
		PrintedTyped Name	Signetan	ANTENNA PROPERTY AND ADDRESS OF THE PARTY OF	Military in the second section of the second section is a second section of the section		dry marineme	Мол	in Clay	Year Year
Ŀ	L			***************************************	TO THE COMMENT OF THE OWNER.	Assessment				
E	PAI	Form 8700-22 (Rev. 3-05) Previous editions are obsolete.					A PPACE	PATOPIS	CATPUTAL	~~~~~

rieas	se print or type. (Form desig	ned for use on elite (12-pitch) t	ypewriter.)												
*	NON-HAZARDOUS WASTE MANIFEST	1. Generalor ID Number		2. Page 1 of		gency Response	hone	4. Waste Tra		ber	2.1	Proposition of the Control of the Co			
	5. Generator's Name and Mallin	ng Address	10 10 X X		Generate	r's Site Address (f different th	an mailing addres:	s)		-				
1000 or Come Notes												aller way and approximate of the state of th			
	Generator's Phone: U.S. EPA ID Number														
	7. Transporter 2 Company Name 8. Designated Facility Name and Site Address									U.S. EPA ID Number					
										O.S. CEATO MURUSI					
	Designated Facility Name at	A**	٠.					U.S. EPÁ ID N	umber						
	Facility's Phone:	33Y9 R			,			r 25		m - 1	· · ·	,			
					······································										
	HM and Packing Group (if	***	e, Hazard Class: ® Number	n r		10. Contain No.	ers Type	11. Total Quantity	12. Unit WL/Vol.			Way 9 March 1980			
N N	1. The first of the second		· · · · · · · · · · · · · · · · · · ·		····					f to Herri					
GENERATOR								41	,	- Target and the state of the s		*			
GEN	2.														
		MANNING CONTRACTOR CON	and the state of t							****	PRESIDENCE PROPERTY AND ADJUSTACE				
	3.									TE T	·				
	4.			rrivatikk vlader Budever lear delerer kissenskinn											
								4							
	13. Spęcjął Handling Instruction	ns and Additional Information	Carlotte Carlotte		3 * . *	A Visit Sarah	को इन्द्रवार ११ इ.स.		de d			····			
		**							I e sessivació	*,					
						<i>t</i> **						-			
						~									
	14. GENERATOR'S CERTIF	ICATION: I certify the materials de	escribed above on this mani			leral reguiations fo	r reporting p	roper disposal of	-lazardous	Wasie.		7,-			
+	Generator's/Offeror's Printed/1	yped Name		S	ignature					Month:	Day	Year			
INT	15. International Shipments Transporter signature (for exp	Import to U.S.		Export from	ı U.S.	Port of en Date leavi									
吊	16, Transporter Acknowledgme							1				Para de la constitución de la co			
PORT	Transporter 1 Printed/Typed N			S	ignature ;					Month	Day	Year			
TRANSPORTER	Transporter 2 Printed/Typed N			3	ignature	<u>i </u>	***************************************	***************************************		Month	Day	Year			
E _*	17. Discrepancy				***************************************		~#************************************								
	17a. Discrepancy Indication S	pace Guantity	Птуре		* Anna proper	Residue		Partial Re	ection	F1444	Full Rejec	otion			
	17b. Alternate Facility (or Gen	Opriori				lanifest Reference	Number:			**************************************					
CILIT	Tro-moundle Facility (of Gen	erator)						U.S. EPA ID I	umber						
ED FA	Facility's Phone: 17c. Signature of Alternate Fa	cility (or Generator)							······································	18.6	· · · · · ·	Vanz			
DESIGNATED FACILITY	The second secon	, to see a second	**************************************		······································	there is no section and the section and				Montf	.Day	Year			
DESIC	* Company of the Comp				,	м.*									
18. Designated Facility Owner or Operator: Certification of receipt of materials covered by the manifest except as noted in Item 17a															
	Printed/Typed Name		a. motoridis operitat by His							Year					
	odb-Millerer				•					. [1			

ate:	23-Feb-2	 017			· · · · · · · · · · · · · · · · · · ·	BILI	L OF LAD	ING	Page 1 of 1
ame: ddress: ity/State/Z	VAL 119 [,] Lip: WHI	SPAR CO 1 S. WHE EELING,	ORP ELING					Bill of Lading Number:	391-02232017
ID#:	391						FОВ:□	CARRIER NAME:	NAME I CALL
				SHIP TO			, 00,	Trailer number:	WILL CALL
ame:	MID	AMERIC	STATE OF THE OWNER, WHEN					Seal number(s)	
ddress:		0 W. COF							
ity/State/Z ID#:	Zip: MIL	WAUKEE	E, WI. 53	209				SCAC:	**************************************
IL/#.							FOB:	Pro number:	
	T	HIRD PA	RTY FR	EIGHT CHA	RGES BI	LL TO		,	en e
ame: .ddress:	VAI P.C	SPAR C BOX 17	/O CAS: '636	SI.S.		and the second s			harges are prepaid unless marked
ity/State/7	Zip: SAI	INT LOUI	S, MO 6	3178-7636				otherwise)	
PECIAL IN	STRUCTIO	NSPROT	ECT FROM	FREEZING	والمعارض المعاولات ومناها والمعارض ومعاهد في		garanga, peka yang kal kalancahan penggan pelanggan pelanggan salam pelanggan salam pelanggan salam salam pelanggan salam sa	Prepaid Colle	ect 3rd Party
									ling with attached underlying Bills of
								(check box) Lading	
					CONTRACTOR OF THE PARTY OF THE		RORDERINE		DED INC
custo	MER ORE	DER NUN	IBER	#PKGS	WEIGH	iT Pallet Slip	1	ADDITIONAL SHIP	PER INFO
		MANUAL PROPERTY OF THE PROPERT			***************************************	Commence of the Commence of th	柯	MTN SHEV	CKIS
						e e junear projection (e es	arraneo de la compositione de la	1 D SIMC	7/3
				e de la companya de l	. •		(000	
	•					aran a same a la companya de la comp		FAFFY	
								9-73-112	
GRAND TO	DTAL							1/	
HANDII	NG UNIT	BAC	KAGE	WEIGHT	. Н.М.	G/AR(I	RIER INFORM	COMMODITY DESCRIP	TIOÑ
QTY	TYPE	QTY	TYPE	~~ -		Commodities	requiring special or	additional care or attention in handling or stowin transportation with ordinary ca See Section 2(e) of NMFC Item	
4	TOTE	4	TOTE	600 LBS	:	EMPTY TO	TES FOR RE		
Application of the contraction of				And a ground of the state of th	May be the supplied of the sup	4	T CONTAINE T ADDITIVE,8	•	
56	TOTE	56	TOTE	8400 LB	s	EMPTY TO	OTES FOR RI	ECYCLE	CORROSIVE
			-	A		1	T CONTAINE		8
		gappy harving				LAII	EX, NOT REG	ULATED	
60		60		9000 LB	s		· · · · · · · · · · · · · · · · · · ·	GRAND TOTAL	
	ial Handi		1		Placards	Offered: Y	Chep P	allets: N	
					*				
Emergen	icy Respoi	nse, 24-ho	our nu m b	er 1-888-748	7-5558 Ou	ıtside af US/	VCanada +1-7	03-527-3887 *** PR C	TECT FROM FREEZIN
value of the	property as fo	oliows:		are required to sta				COD Amount \$ Fee Terms: Colle	ct: Prepaid:
*The agreed	or declared v	value of the pr	roperty is sp	ecifically stated b	y the shipper	to be not exceed	ing	Customer check at	<u> </u>
NOTE	iability l		for loss	or damane	e in this s	shipment m	ay be applica	hble. See 49 U.S.C14706(c)(1)	A) and (B).
SECEMED	authient to int	steh ulleurium	ermined rate	s or contract that rates, classificati	have been ac	greed upon in writ	ing between the	The carrier shall not make delivery of this lawful charges.	shipment without payment of freight and all other
camer and	snipper , if ap are available !	picable , othe to the shipper	, on requesi	rates, classificati t, and to all applic	cable state, fe	deral and provinc	regulations.	Valspar	Shipper Signature
	ER SIGNA				1	iler Loaded: By Sh i pper		Camer acknowledge	NATURE / PICKUP DATE s receipt of packages and required placards. Carrier
accurately	described abo	ive by the pro	per shipping	nent are fully and name, and are	- I	By Driver		Certifies emergency	response information was made available and / or car esponse guidebook or equivalent documentation in th
respectsing	proper condit	ion for transp	ortation acc	ed, and are in all ording to applicab		טy טווע ט ו		vehicle.	above is received in good order, except as noted.
internations	al and nationa	l government	Subations	2/23/	1/5			Oriver/pallets said Property described	


Mid America IBC Milwaukee, Wisconsin 2/24/2017




Photograph #1 - Tote Vacuuming Area




Photograph #2 – Tote Vacuuming Area, Two 250-Gallon Totes with Tote Residues



Photograph #3 – Wash Water Filter Paper Device



Photograph #4 – Two 250-Gallon Toes of Recovered Tote Residue




Photograph #6 – Wash Water Area, 55-Gallon Container Near Filter Paper Area




Photograph #7 – 250-Gallon Totes Waiting To Be Processed




Photograph #8 - Maintenance Shop, Used Fluorescent Lamp Accumulation Area



Photograph #9 - Cut and Scrape Area, Drain Table and 55-Gallon Container



Photograph #10 - Cut and Scrape Area, Tote Saw




Photograph #11 - Cut and Scrape Area, 55-Gallon Containers of Tote Residues



Photograph #12 - Outdoor Tote Storage Prior to Processing




Photograph #13 - Outdoor Tote Storage Prior to Processing (Redacted Company Name)




Photograph #14 – Two 55-Gallon Containers Near Drum Ovens


Mid America IBC Milwaukee, Wisconsin 2/24/2017




Photograph #15 - Old Storage Area Eight 55-Gallon Containers



Photograph #16 - 250-Gallon Tote of Drain Table Residue



Photograph #17 - Cut and Scrape Area Drain Table and 250-Gallon Tote



Photograph #18 - Recertified 250-Gallon Tote M4712